




Res-Up Feedel

INSTALLATION INSTRUCTIONS

- 1. Remove top cover, fill the Res-Up® Feeder (plastic container) to the top with water so that wick retaining clip, tube and wick are wetted, allow to soak for 15 minutes or more.
- 2. Empty water and pull tube and wick through Feeder until slack is removed from inside. The outlet end tube and wick must be below the bottom level of the Res-Up® Feeder.
- 3. Drill TWO 1/4" holes in brine tank as shown in FIGURE 1.
- 4. Drill a 5/8" hole in the brine well cap as shown in FIGURE 2.
- 5. Clip mounting bracket over feeder with "hooks" pointed up. Insert end of tube in the brine well cap and mounting bracket in the 1/4" holes in the brine tank, rotating feeder downward into position as shown in FIGURE 3.
- 6. Fill Feeder with Res-Up® Cleaner to "Fill Line" on label.
- 7. Replace cover on Feeder and automatic feeding will occur in a few hours.









Clack Corporation

4462 DURAFORM LANE • WINDSOR, WISCONSIN 53598-9716 USA PHONE (608) 846-3010 FAX (608) 846-2586 SALES/CUSTOMER SERVICE FAX (800) 755-3010

Form No. S6323 • 10/8/2015